

WebUI

	2025-12					2026-1					2026-2				2026-3				2026-4				2026-5			
	49	50	51	52	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
研发部																										
TD191-B																										
WebUI																										
【Linux】【手工测试】打开linux系统，插入191-B，然后重启系统linux无法上网，重新插拔后恢复。																										
【usb】【手工测试】在surface go2上插着开机测试100次出现2次无法上网																										