

TD191-B

				2025-12				2026-1				2026-2				2026-3				2026-4				2026-5							
				49	50	51	52	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22		
研发部																															
TD191-B																															
WebUI																															
【Linux】【手工测试】打开linux系统，插入191-B，然后重启系统linux无法上网，重新插拔后恢复。																															
【usb】【手工测试】在surface go2上插着开机测试100次出现2次无法上网																															